

Inspection Photos

Loc#323932

Operator: Grizzly

Insp #: 692402386

Insp Date: 7/24/2020





Photo#1:

Overview of Location to East. Insert, view over Well head area.

July 24, 2020



Photo#2:
Unlabeled containers, (some open) and trash/debris
South of Wellhead.



Photo#3:
Open container, full of liquid (indicated with arrow
in Photo#2) and staining.

July 24, 2020



Photo#4:
Unlabeled barrels and staining from unidentified contents.



Photo#5:

July 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly Legg Loc#323932



Photo#6:

View to West, over Tank containment area and Well head, indicated with arrow. Trash/debris, unused equipment scattered throughout Interim areas.



Photo#7:

Trash/Debris South of Well head.

July 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly Legg Loc#323932



Photo#8:
Trash/debris, unused equipment

July 24, 2020



Photo#9:
Trash/debris, along access road entry into Location.



Photo#10:
Weeds that have dried, becoming debris and stored aged woodpile; Well head in upper right corner.



Photo#11:
Scotch & Plumeless thistle (B list Noxious Weeds) were noted on site.

July 24, 2020



Photo#12:
Debris scattered across the site.

July 24, 2020