

# *Inspection Photos*

*Loc#314168*


*Operator: RMNG/Blk Hills*

*Insp #: 692402403*

*Insp Date: 7/27/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Views of Location from entry. Tarp material pile is from remediation excavation.

July 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168



Photo#2:  
Well head area where repairs and cleanup have been conducted.



Photo#3:  
BMPs have been installed/repaired.

July 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168





**Photo#4:**  
Canada thistle established on disturbed perimeters  
of Location.

**Photo#5:**  
Canada thistle established on disturbed perimeters  
of Location.

July 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168





Photo#6:

Area where repairs and cleanup have been conducted. Insert; area 5/28/20.

July 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG/BLK Hills Wolf Creek Loc#314168