

Location Name: – Highball 1 – Location ID 312324

Inspection Date: 07/27/2020



Photo # 1 –

Location Name: – Highball 1 – Location ID 312324
Inspection Date: 07/27/2020



Photo # 2 –



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Highball 1 – Location ID 312324
Inspection Date: 07/27/2020



Photo # 3 – Oil impacted soil on plastic



Location Name: – Highball 1 – Location ID 312324
Inspection Date: 07/27/2020



Photo # 4 – Multiple drums stored with no spill containment



Location Name: – Highball 1 – Location ID 312324
Inspection Date: 07/27/2020



Photo # 5 – Oil stained soil related to wellhead valves

Location Name: – Highball 1 – Location ID 312324
Inspection Date: 07/27/2020



Photo # 6 – Oil stained soil related to wellhead valves



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: – Highball 1 – Location ID 312324
Inspection Date: 07/27/2020



Photo # 7 – Produced water pit with no pit permit on file



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources