

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/04/2020

Submitted Date:

08/04/2020

Document Number:

701001105

**FIELD INSPECTION FORM**

Loc ID 321708 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77269

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207828	WELL	PR	12/01/1989	OW	017-06763	ARAPAHOE UNIT 122(22-31)	PR

**General Comment:**

Routine Inspection

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal fence around unit and stairs to wellhead		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type:	Horizontal Separator	# 1	corrective date
Comment:	80bbl separator in metal shed on south side of vertical treater		
Corrective Action:		Date:	
Type:	Prime Mover	# 1	
Comment:	Electric motor		
Corrective Action:		Date:	
Type:	Pump Jack	# 1	
Comment:	Lufkin 228		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	Meter run on north side of treaters		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:	100bbl treater with metal shed		
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Electric panel, cathodic rectifier and telemetry equipment, electric circ pump in metal shed at battery		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.790050,-102.052760
Comment:	300bbl overflow tank on south side of 400bbl tank				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		38.790050,-102.052760
Comment:	Water tanks are on north side of location				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	2	400 BBLs	STEEL AST		38.789760,-102.052780
Comment: 1-Blue tank 1-Tan tank					
Corrective Action:					Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No					
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

**Inspected Facilities**

Facility ID: 207828 Type: WELL API Number: 017-06763 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central tank battery for Arapahoe Unit \(121 & 122\) 1900' W @ 38.78976/-102.05278](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT