

Inspection Photos
Operator: Hilcorp Energy
API: 067-09383
Date: 7/28/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of unknown material approximately 5 feet wide and 15 feet long on the well pad.



Photo 3. View of wattles along the eastern edge of the project area that are no longer functioning and are not adequate BMPs in this area.



Photo 4. View of wattles in the southeastern project area that are no longer functioning and are not adequate BMPs in this area.



Photo 5. View of reference area vegetation comprised of pinyon and juniper woodland, with black sage, blue grama, and *Tetaneuris* sp.