





39.68668, -108.93678, 6623.5ft, 317°
08/04/2020 12:32:12 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Location.

Sloan Government 1

API: 05-103-05005

Inspection: 700402746



D&G ROUSTABOUT SERVICE CO.
SLOAN GOVT. #1
NE 1/4 NE 1/4 SEC. 27, T4S, R103W
RIO BLANCO COUNTY, CO
LEASE # 000-02756
EMERGENCY PHONE # 970-858-1581

39.68669, -108.93685, 6623.3ft, 28°
08/04/2020 12:24:21 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well.

Sloan Government 1

API: 05-103-05005

Inspection: 700402746




39.68671, -108.93681, 6608.2ft, 306°
08/04/2020 12:24:40 PM





39.68694, -108.93724, 6660.5ft, 59°
08/04/2020 12:27:37 PM





39.68681, -108.93702, 6632.5ft, 299°

08/04/2020 12:31:26 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Photo 8. ~2 inches of fluid at bottom of tank /
pit.**

Sloan Government 1

API: 05-103-05005

Inspection: 700402746



Meter # 93997 Station Name Government Sloan #1

Sec 27 Twn 4S Rng 103W County Rio Blanco State CO Elev 6720

Customer DG Paustabout Atmo: 115 A/G 1 Radio _____

Model# _____ Make Barton Tube Size 2.067

Transducer Range: Diff: _____ Static _____ Tap Location - Up _____ Down

Calibrated Range: Diff 100" Static 500" Temp 150° Absolute Gauge _____

Lease# C-02756 Tech C. Jackson Phone 303-525-6702

Notes: _____

39.68694, -108.93705, 6628.7ft, 118°
08/04/2020 12:28:11 PM