

Inspection Photos

API: 071-08360

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 1. Facing west toward the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 2. Facing west along the road ascending the hill. It appears stormwater is not properly directed toward the culvert causing erosion down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 3. Facing northeast toward the location. There are areas bare of vegetation at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 4. Facing toward the cut slope at the location. Vegetation has not adequately established and there are signs of erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 5. Facing north along the cut slope. Vegetation has not adequately established along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 6. Facing southeast toward the location. A permanent well marker is installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 7. This area next to the well marker is bare of vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 8. East side of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020

Inspection Photos



Photo 9. Facing west toward the surrounding undisturbed vegetation which consists of Blue grama grass, Mtn mohogany shrubs, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08360 | Date: 8/3/2020