

Inspection Photos

API: 071-06799

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06799 | Date: 8/3/2020

Inspection Photos




Photo 1. Facing southeast along CR 41.7. This area has been regraded and outlet protection has been installed at the culvert shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06799 | Date: 8/3/2020

Inspection Photos



Photo 2. Facing toward the beginning of the access road. The cattle guard has been cleaned out and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06799 | Date: 8/3/2020

Inspection Photos



Photo 3. Facing southeast along the access road. Rock check dams have been installed along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06799 | Date: 8/3/2020

Inspection Photos



Photo 4. Facing toward the culvert outlet. The erosion from the culvert has been repaired. A sediment trap has been installed and culvert outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06799 | Date: 8/3/2020

Inspection Photos



Photo 5. Facing southeast toward the location. The sediment trap has been cleaned out and maintained and rip/rap has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06799 | Date: 8/3/2020