

Inspection Photos

API: 071-06798

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/3/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06798 | Date: 8/3/2020

Inspection Photos



Photo 1. Facing southeast along the access road. Rock check dams have been installed along the side of the road where erosion was occurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06798 | Date: 8/3/2020

Inspection Photos



Photo 2. Facing east along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06798 | Date: 8/3/2020

Inspection Photos



Photo 3. The rock check dams have been installed and repaired. The check dams will need to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06798 | Date: 8/3/2020

Inspection Photos



Photo 4. The area of erosion along the road has been stabilized with rock rip/rap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06798 | Date: 8/3/2020

Inspection Photos



Photo 5. Facing southeast along the opposite side of the road. Rock check dams have been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06798 | Date: 8/3/2020