

Inspection Photos  
Location Name: Sam Funakoshi A #2  
Location ID: 318283



Photo 1 Updated WH sign

Photo 2 stained soil has been removed from around WH

Inspection Photos  
Location Name: Sam Funakoshi A #2  
Location ID: 318283



Photo 3 Pump Jack



Photo 4 weeds have been removed from meter box and transformer area.