

**Inspection Photos**  
**Location Name: Speaker West PAD**  
**Location ID: 434773**



**Photo 1 – Pumping Units**



**Photo 2 – Pumping Units, Weeds at Wellhead**



**Inspection Photos**  
**Location Name: Speaker West PAD**  
**Location ID: 434773**



**Photo 3 – East Heater Treater**



**Photo 4 – Tank Battery**



**Inspection Photos**  
**Location Name: Speaker West PAD**  
**Location ID: 434773**



**Photo 5 – West Heater Treater**



**Photo 6 – Stained Soil inside West Heater Treater**



**Inspection Photos**  
**Location Name: Speaker West PAD**  
**Location ID: 434773**



**Photo 7 – Stained Soil at Pumping Unit Exhaust**