

Inspection Photos
Location Name: Speaker East PAD
Location ID: 424603



Photo 1 – Pumping Units/Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: Speaker East PAD
Location ID: 424603



Photo 3 – Day Tank at Compressor missing Wildlife Netting