

Inspection Photos
Location Name: Debrine 21-44-8-61
Location ID: 424270



Photo 1 – Pumping Units/Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: Debrine 21-44-8-61
Location ID: 424270



Photo 3 – Produced Water Tank – Content and Capacity have faded no longer visible

Photo 2 – Tank Battery Sign