

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2020

Submitted Date:

08/05/2020

Document Number:

700701281

**FIELD INSPECTION FORM**Loc ID 334695 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		sgshan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284937	WELL	PR	01/07/2007	GW	045-12212	CIRCLE B LAND 24B-35-692	PR
285171	WELL	PR	01/08/2007	GW	045-12384	CIRCLE B LAND 14A-35-692	PR
285172	WELL	PR	01/08/2007	GW	045-12385	CIRCLE B LAND 24D-35-692	PR
285175	WELL	PR	01/09/2007	GW	045-12383	CIRCLE B LAND 14C-35-692	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 8/5/20 at approximately 1230, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Circle B 5, at Location # 334695 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

This is a summary of inspection report.

### Location

**Lease Road:**

	Type Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

	Type CONTAINERS		
Comment:			
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	
	Type BATTERY		
Comment:			
Corrective Action:		Date:	
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume			
------	------	--------	--	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	
	Type SEPARATOR		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	
Type	IGNITOR/COMBUSTOR			
Comment:				
Corrective Action:			Date:	

**Equipment:**

			corrective date
Type: Gas Meter Run	# 4		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	80 bbl tank hooked to a bradenhead				
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Inspector Name: Ramsey, Scott

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	8	OTHER	HEATED STEEL AST		,	
Comment:		250 bbl tanks				
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type	Ignitor/Combustor					
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	284937	Type:	WELL	API Number:	045-12212	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	285171	Type:	WELL	API Number:	045-12384	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	285172	Type:	WELL	API Number:	045-12385	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	285175	Type:	WELL	API Number:	045-12383	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	producing								
Corrective Action:						Date:			

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Check Dams				
Gravel		Ditches				
Ditches		Culverts				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701290	Photos for Circle B5	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5218716">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5218716</a>