

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402430194

Date Received:  
06/29/2020

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Pesicka, Conor</u>		<u>conor.pesicka@state.co.us</u>
<u>.</u>		<u>dnr_cogccengineering@state.co.us</u>
<u>Distribution, Evergreen</u>		<u>cogcc.evergreen@enrllc.com</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 695101764  
Inspection Date: 11/18/2019 FIR Submit Date: 11/18/2019 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: EVERGREEN NATURAL RESOURCES LLC Company Number: 10705  
Address: 1801 BROADWAY SUITE 350  
City: DENVER State: CO Zip: 80202

**LOCATION - Location ID: 308480**

Location Name: T.Y.L.-632S66W Number: 27SENE County: LAS ANIMAS  
Qtrqtr: SENE Sec: 27 Twp: 32S Range: 66W Meridian: 6  
Latitude: 37.229760 Longitude: -104.761480

**FACILITY - API Number: 05-071-00 Facility ID: 272702**

Facility Name: T.Y.L. Number: 42-27  
Qtrqtr: SENE Sec: 27 Twp: 32S Range: 66W Meridian: 6  
Latitude: 37.229760 Longitude: -104.761480

**CORRECTIVE ACTIONS:**

**1**  CA# 134688

Corrective Action: REMOVE UNUSED EQUIPMENT ASS PER NTO AND RULE 603.f. Date: 02/18/2020

Response: CA COMPLETED Date of Completion: 02/18/2020

Operator Comment: Removed unused equipment, to comply with Rule 603.f.

COGCC Decision: Approved pending re-inspection

COGCC Representative: APPROVED BASED ON PHOTO SUBMITTED BY OPERATOR.

2  CA# 134689

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 12/18/2019

Response: CA COMPLETED

Date of Completion: 12/05/2019

Operator Comment: Performed a mechanical Integrity test per rule 326 and 208

COGCC Decision: Approved via an AMI

COGCC Representative: APPROVED BASED ON DOCUMENTATION SUBMITTED BY OPERATOR.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached Photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susan Wolfram

Signed: \_\_\_\_\_

Title: Sr. Safety Coordinator

Date: 6/29/2020 9:56:30 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402430194	FIR RESOLUTION SUBMITTED
402430197	Form 21 402255075
402433277	T.Y.L. 42-27

Total Attach: 3 Files