

# Reclamation Inspection

August 5, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 287848

Inspection Document #: 697501850

Weld County, CO

NWNW Section 18 T4N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

# Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 1.** Photo taken from the northeastern fenced perimeter of the location. Photo illustrates the Operator sign. There was another sign observed off of CR 46.



## Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 2.** Photo taken from the main point of access to the facility, facing South. Photo illustrates an inaccurate sign. Other inaccurate signs were observed.

# Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 3.** Photo taken from the main point of access to the facility, facing West. Photo illustrates unmanaged stormwater run-on onto the facility.

Note: There was stormwater run-off from the southern facility.



# Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 4.** Photo taken from the western facility, facing West. Photo illustrates the perimeter fence has a breach to control public access.

# Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 5.** Photo taken from the western facility, facing West. Photo illustrates the perimeter fence entry is open.



# Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 6.** Photo taken from the northeastern detention pond located along the western boundary of the facility, facing North. Photo illustrates a List B Colorado noxious weed, Leafy spurge.



Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 7.** Close up photo illustrating Leafy spurge.



## Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 8.** Photo taken from the central facility area, facing East. Photo illustrates a List B Colorado noxious weed, Scotch thistle. Photo also illustrates a List C Colorado noxious weed, Cheatgrass, in the foreground and background.



# Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 9.** Photo taken from the central facility area, facing Northeast. Photo illustrates a patch of Scotch thistle.



Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



**Photo 10.** Photo taken from the central facility area. Photo illustrates a List B Colorado noxious weed, Musk thistle.