

# *Inspection Photos*

*Loc#314167*

*Operator: RMNG/Blk Hills*

*Insp #: 692402405*

*Insp Date: 7/27/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry; Camper & License Plate.

July 27, 2020





Photo#2:  
Stormwater concerns at SE corner of Pad



Photo#3:  
Stormwater concerns at SE corner of Pad.

July 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMNG/BLK Hills Wolf Creek Loc#314167





Photo#4:  
Stormwater concerns at SE corner of Pad.



Photo#5:  
Initiation of erosion on Cut slope.

July 27, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMNG/BLK Hills Wolf Creek Loc#314167