

Inspection Photos
Operator: WPX Energy
API: 067-08089
Date: 8/3/2020



Photo 1. View of the reclaimed project area from the northwestern corner facing center. Revegetation is becoming established with blue grama, little bluestem, fourwing saltbush, Indian ricegrass, tarragon, *Heterotheca villosa*, and crested wheatgrass.



ge

Photo 2. View of the reclaimed project area from the well pad entrance facing center.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the eastern project area from the northeastern corner facing southward.



Photo 5. View of the well pad access road facing southward.



Photo 6. View of reference area vegetation comprised of pinyon and juniper woodland, with antelope bitterbrush, sagebrush, blue grama, Indian ricegrass, sulferflower buckwheat, and gambel oaks in the understory.