

Inspection Photos
Operator: Logos Operating
API: 067-09055
Date: 8/3/2020



Photo 1. View of the project area from the southeastern corner facing center.



ge

Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with fourwing saltbush, crested wheatgrass, juniper, and western wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area vegetation comprised of pinyon juniper woodland with sagebrush and blue grama in the understory.