

Inspection Photos
Location Name: Ptasnik 1-30-9-59 PAD
Location ID: 441041



Photo 1 – Wellheads



Photo 2 – Maintenance Tank, Current 24 Hour Emergency # missing, Capacity not current, Content missing