

**Inspection Photos**  
**Location Name: Peggy 2501 PAD**  
**Location ID: 462872**



**Photo 1 – Wellheads, Stained Soil**



**Photo 2 – Tanks**

Inspection Photos  
Location Name: Peggy 2501 PAD  
Location ID: 462872



Colorado Oil and Gas Conservation Commission  
40.71511, -104.04076, 4837.9ft, 227°  
08/04/2020 13:25:54



Colorado Oil and Gas Conservation Commission  
40.71513, -104.04088, 4843.7ft, 267°  
08/04/2020 13:25:08

Photo 4 – Separators

Photo 4 – Tank Battery Sign

Inspection Photos  
Location Name: Peggy 2501 PAD  
Location ID: 462872



Photo 5 – Tank Battery Sign