

Inspection Photos
Location Name: Shull 1-25-9-60 PAD
Location ID: 432177



Photo 1 – Wellheads, Stained Soil




Photo 2 – East Compressor, Stained Soil, Methanol Tank missing Wildlife Netting



Inspection Photos
Location Name: Shull 1-25-9-60 PAD
Location ID: 432177



Photo 3 – East Wellheads



Photo 4 – West Wellheads

Inspection Photos
Location Name: Shull 1-25-9-60 PAD
Location ID: 432177



Photo 5 – East Heater Treaters



Photo 6 – East Tanks

Inspection Photos
Location Name: Shull 1-25-9-60 PAD
Location ID: 432177



Photo 7 – West Compressors



Photo 8 – Methanol Missing Wildlife Netting

Inspection Photos
Location Name: Shull 1-25-9-60 PAD
Location ID: 432177



Photo 9 – Methanol Missing Wildlife Netting



Photo 10 – West Heater Treaters

Inspection Photos
Location Name: Shull 1-25-9-60 PAD
Location ID: 432177



Photo 11 – West Tanks



Photo 12 – Middle Heater Treaters