

# Inspection Photos

8/04/2020

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 322524

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 322524



**Photo 1:** Photo taken from the west end of the Location, facing north. Photos 1-3 provide an overview of the Location from North, northeast to east.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 322524



**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 322524



**Photo 3:** See comments under photo 1. Well shares are with active Nonsuch Location;  
Areas around well remain needed for Nonsuch operations.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 322524



**Photo 4:** Photo taken from the west end of the Location, facing north. Photo shows noxious weeds; Weed management (spraying) activities evident.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 322524



**Photo 5:** Photo taken from the west end of the Location, facing north. Photo shows noxious weeds; Weed management (spraying) activities evident.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 322524



**Photo 6:** Photo taken from the west end of the Location, facing west. Photo shows freshwater pit. Photo shows noxious weeds; Weed management (spraying) activities evident.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 322524



**Photo 7:** Photo taken from the west end of the Location, facing northwest. Photo shows freshwater pit. Photo shows noxious weeds; Weed management (spraying) activities evident.