

# Inspection Photos

8/04/2020

Operator: NONSUCH NATURAL GAS INC #  
10163

Location ID: 453726  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



**Photo 1:** Photo taken from the Location, facing southwest. Photo shows production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



**Photo 2:** Photo taken from the west end of the Location, facing south. Photo shows noxious weeds (Musk thistle). Weeds appear to have been sprayed and show signs of senescence.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



**Photo 3:** Photo of 200 bbl condensate tank. Photo shows vegetative establishment within and on secondary containment. Vegetative establishment within compromises the imperviability of the containment per rule 906.d.(1). Containment BMP does not appear to be sufficient to contain contents of tank and sufficient freeboard to contain precipitation.



Inspection Photos  
Operator Name: NONSUCH NATURAL GAS INC # 10163  
Location ID: 453726



**Photo 4:** See comment under photo 3.





## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC # 10163

Location ID: 453726



**Photo 5:** Photo taken from the Location, facing east. Photo shows trailer on location. This is equipment not needed for production and requires removal.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources