

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2020

Submitted Date:

08/09/2020

Document Number:

701100143

FIELD INSPECTION FORM

Loc ID Inspector Name: On-Site Inspection ☐
 416157 LONGWORTH, MIKE 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

23 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416001	WELL	PR	07/01/2017	GW	045-19203	697-26A 21	PR
416167	WELL	PR	07/01/2017	GW	045-19225	697-26A 14	PR
416169	WELL	SI	08/01/2018	GW	045-19227	697-26A 23	PR
416172	WELL	PR	07/01/2017	GW	045-19229	697-26A 12	PR
448164	WELL	PR	12/01/2018	OG	045-23353	Puckett 34C-23-697	PR
448165	WELL	PR	09/23/2017	GW	045-23354	Puckett 21D-26-697	PR
448166	WELL	SI	04/01/2020	OG	045-23355	Puckett 33C-26-697	SI
448167	WELL	PR	12/01/2018	OG	045-23356	Puckett 35A-23-697	PR
448168	WELL	PR	12/01/2018	OG	045-23357	Puckett 32D-26-697	PR
448169	WELL	PR	08/29/2017	GW	045-23358	Puckett 32A-26-697	PR
448170	WELL	PR	08/21/2017	OG	045-23359	Puckett 21A-26-697	PR
448171	WELL	PR	09/10/2017	GW	045-23360	Puckett 32B-26-697	PR
448172	WELL	PR	08/29/2017	OG	045-23361	Puckett 31C-26-697	PR
448173	WELL	PR	12/01/2018	OG	045-23362	Puckett 33B-26-697	PR
448174	WELL	PR	08/29/2017	OG	045-23363	Puckett 21B-26-697	PR
448175	WELL	PR	09/10/2017	GW	045-23364	Puckett 22D-26-697	PR
448177	WELL	PR	12/01/2018	OG	045-23366	Puckett 32C-26-697	PR
448178	WELL	PR	12/01/2018	OG	045-23367	Puckett 34D-23-697	PR
448179	WELL	PR	09/21/2017	GW	045-23368	Puckett 22C-26-697	PR
448180	WELL	PR	12/01/2018	OG	045-23369	Puckett 35B-23-697	PR
448181	WELL	PR	12/01/2018	OW	045-23370	Puckett 33A-26-697	PR

448182	WELL	PR	09/04/2017	OG	045-23371	Puckett 22B-26-697	PR
--------	------	----	------------	----	-----------	--------------------	----

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities				
Facility ID: 416001	Type: WELL	API Number: 045-19203	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 416167	Type: WELL	API Number: 045-19225	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 416169	Type: WELL	API Number: 045-19227	Status: SI	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 416172	Type: WELL	API Number: 045-19229	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 448164	Type: WELL	API Number: 045-23353	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 448165	Type: WELL	API Number: 045-23354	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 448166	Type: WELL	API Number: 045-23355	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment:				
Corrective Action:				Date: _____
Facility ID: 448167	Type: WELL	API Number: 045-23356	Status: PR	Insp. Status: PR

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 448168 Type: WELL API Number: 045-23357 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 448169 Type: WELL API Number: 045-23358 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 448170 Type: WELL API Number: 045-23359 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 448171 Type: WELL API Number: 045-23360 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 448172 Type: WELL API Number: 045-23361 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 448173 Type: WELL API Number: 045-23362 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 448174 Type: WELL API Number: 045-23363 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 448175 Type: WELL API Number: 045-23364 Status: PR Insp. Status: PR				

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	448177	Type:	WELL	API Number: 045-23366 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	448178	Type:	WELL	API Number: 045-23367 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	448179	Type:	WELL	API Number: 045-23368 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	448180	Type:	WELL	API Number: 045-23369 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	448181	Type:	WELL	API Number: 045-23370 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	448182	Type:	WELL	API Number: 045-23371 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
Compaction	Pass					
		Culverts	Pass			
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701100171	Inspection 701100143 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219723