

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2020

Submitted Date:

08/09/2020

Document Number:

701100145

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 448472 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

34 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448452	WELL	PR	11/02/2018	OG	045-23396	Puckett 24D-26-697	PR
448453	WELL	PR	11/05/2018	OG	045-23397	Puckett 34B-26-697	PR
448454	WELL	PR	09/22/2018	OG	045-23398	Puckett 12C-26-697	PR
448455	WELL	PR	11/19/2018	OG	045-23399	Puckett 35B-26-697	PR
448456	WELL	PR	10/30/2018	OG	045-23400	Puckett 24C-26-697	PR
448457	WELL	PR	10/17/2018	OG	045-23401	Puckett 14B-26-697	PR
448458	WELL	PR	10/21/2018	OG	045-23402	Puckett 33D-26-697	PR
448459	WELL	PR	10/25/2018	OG	045-23403	Puckett 34A-26-697	PR
448460	WELL	PR	09/18/2018	OG	045-23404	Puckett 12B-26-697	PR
448461	WELL	PR	10/07/2018	OG	045-23405	Puckett 23A-26-697	PR
448462	WELL	PR	10/23/2018	OG	045-23406	Puckett 14C-26-697	PR
448463	WELL	PR	11/07/2018	OG	045-23407	Puckett 15A-26-697	PR
448464	WELL	PR	09/24/2018	OG	045-23408	Puckett 13A-26-697	PR
448465	WELL	PR	11/15/2018	OG	045-23409	Puckett 15B-26-697	PR
448466	WELL	PR	09/18/2018	OG	045-23410	Puckett 11D-26-697	PR
448467	WELL	PR	11/10/2018	OW	045-23411	Puckett 35A-26-697	PR
448468	WELL	PR	11/04/2018	OG	045-23412	Puckett 34C-26-697	PR
448469	WELL	PR	09/29/2018	OG	045-23413	Puckett 13B-26-697	PR
448470	WELL	PR	10/10/2018	OG	045-23414	Puckett 14A-26-697	PR
448471	WELL	PR	10/07/2018	OG	045-23415	Puckett 23C-26-697	PR
448473	WELL	PR	09/28/2018	OG	045-23416	Puckett 13C-26-697	PR

448474	WELL	PR	09/18/2018	OG	045-23417	Puckett 12A-26-697	PR
448475	WELL	PR	10/11/2018	OG	045-23418	Puckett 13D-26-697	PR
448476	WELL	PR	09/30/2018	OG	045-23419	Puckett 23B-26-697	PR
448477	WELL	PR	10/12/2018	OG	045-23420	Puckett 23D-26-697	PR
448478	WELL	PR	09/22/2018	OG	045-23421	Puckett 12D-26-697	PR
448479	WELL	PR	10/21/2018	OG	045-23422	Puckett 24A-26-697	PR
448480	WELL	PR	11/14/2018	OG	045-23423	Puckett 25B-26-697	PR
448481	WELL	PR	12/14/2018	OW	045-23424	Puckett 34D-26-697	PR
448482	WELL	PR	10/29/2018	OG	045-23425	Puckett 14D-26-697	PR
448483	WELL	PR	10/24/2018	OG	045-23426	Puckett 24B-26-697	PR
448484	WELL	PR	11/07/2018	OW	045-23427	Puckett 25A-26-697	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	448452	Type:	WELL	API Number:	045-23396	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448453	Type:	WELL	API Number:	045-23397	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448454	Type:	WELL	API Number:	045-23398	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448455	Type:	WELL	API Number:	045-23399	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448456	Type:	WELL	API Number:	045-23400	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448457	Type:	WELL	API Number:	045-23401	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448458	Type:	WELL	API Number:	045-23402	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448459	Type:	WELL	API Number:	045-23403	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	448460	Type:	WELL	API Number:	045-23404	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448461	Type:	WELL	API Number:	045-23405	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448462	Type:	WELL	API Number:	045-23406	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448463	Type:	WELL	API Number:	045-23407	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448464	Type:	WELL	API Number:	045-23408	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448465	Type:	WELL	API Number:	045-23409	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448466	Type:	WELL	API Number:	045-23410	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448467	Type:	WELL	API Number:	045-23411	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	448468	Type:	WELL	API Number:	045-23412	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448469	Type:	WELL	API Number:	045-23413	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448470	Type:	WELL	API Number:	045-23414	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448471	Type:	WELL	API Number:	045-23415	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448473	Type:	WELL	API Number:	045-23416	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448474	Type:	WELL	API Number:	045-23417	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448475	Type:	WELL	API Number:	045-23418	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448476	Type:	WELL	API Number:	045-23419	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	448477	Type:	WELL	API Number:	045-23420	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448478	Type:	WELL	API Number:	045-23421	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448479	Type:	WELL	API Number:	045-23422	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448480	Type:	WELL	API Number:	045-23423	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448481	Type:	WELL	API Number:	045-23424	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448482	Type:	WELL	API Number:	045-23425	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448483	Type:	WELL	API Number:	045-23426	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	448484	Type:	WELL	API Number:	045-23427	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
Compaction	Pass					
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701100173	inspection 701100145 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219725