

Inspection Photos

Loc#413453

Operator: Grizzly

Insp #: 692402389

Insp Date: 7/24/2020



Photo#1:
Overview of Location to Northeast.

July 24, 2020



Photo#2:

View to Southeast along bale barrier that is becoming debris and unsafe; insert East end of row.

July 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly Kauffman Loc#413453



Photo#3:
Wattles that have become debris.



Photo:#4
Wattles that have become debris

July 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly Kauffman Loc#413453



Photo#5:
Wattles that have become debris.

July 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#6:
Wattles that have become debris.

Inspection Photos: Grizzly Kauffman Loc#413453



Photo#7:
Noxious weeds, Scotch thistle scattered on site.



Photo#8:
Noxious weeds, Knapweed on South slope.

July 24, 2020



Photo#9:
Repair, parts equipment not properly stored.




Photo#10:
Supplies, parts not properly stored

July 24, 2020



Photo#11:
New ramp?

July 24, 2020



Photo#12:
New ramp?