

Inspection Photos

Loc#335290

Operator: Grizzly

Insp #: 692402390


Insp Date: 7/24/2020



Photo#1:

Overview of Location to Southeast. Note Kochia (debris weed) on both sides of access road.

July 24, 2020



Photo#2:
Heavy old growth in Interim areas.

July 24, 2020



Photo#3:
Debris and Noxious weed growth.

Photo#4:
Debris and Noxious weed growth

July 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly GGU Loc#335290



Photo#5:
Three Anchors are not Marked.

July 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly GGU Loc#335290