

Inspection Photos  
Operator: BP America  
API: 067-09017  
Date: 8/5/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass, and crested wheatgrass.





Photo 3. View of the northwestern project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of black sage, blue grama, gambel oak, snakeweed, and yellow rabbitbrush.