

Inspection Photos
Operator: BP America
API: 067-08704
Date: 8/5/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Interim reclamation is recently conducted with hay mulch and young grass seedlings observed.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of black sage, blue grama, gambel oak, snakeweed, and yellow rabbitbrush.