

BP L48 San Juan



V2 Compliance Follow Up Form

18150785000

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200806-18150785000

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 6, 2020 1:33:35 PM MDT

14908 US-550, Durango, CO 81303, USA

Aug 6, 2020 1:28:54 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 6, 2020
Well Name	CRAIG GAS UNIT 1 DK
Location Name (Other)	CRAIG GAS UNIT 3
API Number	50670606700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Replaced/Repaired Tank Signs
Photo of first corrective action completed	



**Completed work description Corrective
Action 1**

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Installed new tank sign

Photo of third corrective action completed



Completed work description of corrective action 3

Replaced tank sign

Photo of fourth corrective action completed



Completed work description

Replaced tank sign

Completed work description of corrective action 4

Replaced tank sign

Summary of all work completed

Compliance, replaced pit tank sign.