



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date: Aug 7, 2020 10:57:03 AM MDT
Server Receive Date: Aug 7, 2020 10:57:49 AM MDT
Reference Number: 20200807-18150871079
Location: 7947 CO-151, Ignacio, CO 81137, USA
Aug 7, 2020 10:52:55 AM MDT [[View Map](#)]

Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 5, 2020
Well Name	SO UTE 29- 1 2 GAS UNIT
API Number	50670678300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1
Photo of second corrective action completed

Compliance



Completed work description of corrective action 2
Photo of third corrective action completed

Installed diversion ditch



Completed work description of corrective action 3
Photo of fourth corrective action completed

Built rock run downs



Completed work description
Completed work description of corrective action 4
Additional photos

Cleaned up stains
Marked anchors



Additional photos



Summary of all work completed

Compliance, installed diversion ditch , clean up stains , removed weeds , picked up trash fixed erosion and built rock run down