

Inspection Photos
Location Name: Nelson17-44-9-60 PAD
Location ID: 422744



Photo 1 – Tank Battery Sign at Entrance, Weeds



Photo 2 – Pumping Units

Inspection Photos
Location Name: Nelson17-44-9-60 PAD
Location ID: 422744



Photo 3 – Tank Battery



Photo 4 – Weeds in Reclamation Area

Inspection Photos
Location Name: Nelson17-44-9-60 PAD
Location ID: 422744



Photo 5 – Weeds in Reclamation Area



Photo 6 – Weeds in Reclamation Area

Inspection Photos
Location Name: Nelson17-44-9-60 PAD
Location ID: 422744



Photo 7 – Weeds in Reclamation Area



Photo 8 – Weeds in Reclamation Area