

Inspection Photos  
Location Name: Nelson 2-17-9-60 PAD  
Location ID: 431925



Photo 1 – Tank Battery Sign



Photo 2 – Pumping Units



**Inspection Photos**  
**Location Name: Nelson 2-17-9-60 PAD**  
**Location ID: 431925**



**Photo 3 – Heater Treaters**



**Photo 4 – Tank Battery**



**Inspection Photos**  
**Location Name: Nelson 2-17-9-60 PAD**  
**Location ID: 431925**



**Photo 5 – 3-17-9-60 Wellhead – Weeds. Missing Sign**



**Photo 6 – Southwest Water Tanks – Missing Content and Capacity**

**Inspection Photos**  
**Location Name: Nelson 2-17-9-60 PAD**  
**Location ID: 431925**



**Photo 7 – Weeds at the back of Pumping Unit**



**Photo 8 – North Tanks missing Content and Capacity**



**Inspection Photos**  
**Location Name: Nelson 2-17-9-60 PAD**  
**Location ID: 431925**



**Photo 9 – Weeds in Reclamation Area**



**Photo 8 – Weeds in Reclamation Area**

**Inspection Photos**  
**Location Name: Nelson 2-17-9-60 PAD**  
**Location ID: 431925**



**Photo 11 – Weeds in Reclamation Area**



**Photo 12 – Weeds in Reclamation Area**