

BP L48 San Juan



V2 Compliance Follow Up Form

18151072915

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200810-18151072915

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 10, 2020 3:13:20 PM MDT

1013 Co Rd 308, Durango, CO 81303, USA

Aug 10, 2020 3:05:40 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 7, 2020
Well Name	LUNT GAS UNIT 19-01 2
API Number	50670879000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Install Rock Run Down Clean up Operator Debris Clean Up Weed Debris Clean Up Contaminated Soils Spot seeding
Photo of first corrective action completed	



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective
action 2**

Installed rock run down

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Removed weeds

Photo of fourth corrective action completed



Completed work description

Built diversion ditch

Completed work description of corrective action 4

Spot seeded bare areas on location

Additional photos



Additional photos

**Summary of all work completed**

Compliance, cleaned up trash , spot seeding ,
installed diversion ditch and sediment bowls