


Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 334867



Tank battery removed and flowlines

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 334867



Well heads and risers removed

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 334867



Separators and risers removed