

Inspection Photos

Loc#314169

Operator: RMNG/Blk Hills

Inspection #:692402417

Inspection Date: 7/27/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

July 27, 2020



Photo#2:
Tracking off Pad into Interim area 5/28/20.



Photo#3:
Tracking off Pad into Interim and BMPs
7/27/20.

July 27, 2020



Photo#4:
Amount of sediment migration is occurring along access road ditches and base of cut.

July 27, 2020



Photo#5:
Amount of sediment migration is occurring along access road ditches and base of cut.