

# Final Reclamation Inspection

August 5, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 319367

Inspection Document #: 697501861

Weld County, CO

NENW Section 24 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KENT #1  
Location ID: 319367



**Photo 1.** Photo taken from the associated offsite tank battery, facing South. Photo illustrates culverts and gravel piles. It is unclear whether this is from the Operator or surface owner.

Inspection Photos  
Location Name: KENT #1  
Location ID: 319367



**Photo 2.** Photo taken from the well location access road, facing South. Photo illustrates crop growth appears reflective of reference areas. Staff did not inspect the well location. The well location has an active remediation project (REM Project #14520).