

Final Reclamation Inspection

August 10, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 335954

Inspection Document #: 697501863

Weld County, CO

NWNW Section 18 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HINGLEY #2J
Location ID: 335954



Photo 1. Photo taken from the western access road, facing East. Photo illustrates the Operator has failed to recontour the access road, as well as control undesirable weeds. Note- it does not appear the surface owner is using the access road; surface owner is driving north of the access road with the evidence of agricultural activities (green arrows). Also, refer to Photos 4-6.

Inspection Photos
Location Name: HINGLEY #2J
Location ID: 335954



Photo 2. Photo taken from the central access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: HINGLEY #2J
Location ID: 335954



Photo 3. Photo taken from the northern location, facing East. Photo illustrates where the former tank was. Operator has failed to recontour the location.

Inspection Photos
Location Name: HINGLEY #2J
Location ID: 335954



Photo 4. Photo taken from the northern location, facing West. Photo illustrates the oil and gas access road that is no longer being used. Surface owner is driving north of the access road with the evidence of agricultural activities.

Inspection Photos
Location Name: HINGLEY #2J
Location ID: 335954



Photo 5. Photo taken from the central access road, facing West. See comments under Photo 4.

Inspection Photos
Location Name: HINGLEY #2J
Location ID: 335954



Photo 6. Photo taken from the western access road, facing East. See comments under Photo 4.