

Inspection Photos
Location Name: UTE CANYON 12-3
API#: 05-071-09495
INSP. #: 695103143143



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: UTE CANYON 12-3
API#: 05-071-09495
INSP. #: 695103143143



PHOTO 3: PIT LINER IS IN DISREPAIR. REMOVE OR REPLACE LINER, COMPLY WITH RULE 904. CA DATE 11-11-20.

PHOTO 4: ANOTHER IMAGE FOR PIT LINER CA MENTIONED IN PHOTO 3.

Inspection Photos

Location Name: UTE CANYON 12-3

API#: 05-071-09495

INSP. #: 695103143143



**PHOTO 5: SMALL PIECED OF PIT LINER FOUND OF LOCATION
IN INTERIM RECLAMATION AREA. POLICE LOCATION AND
SURROUNDING AREA FOR ANY TRASH AND DISPOSE,
COMPLY WITH RULE 603.f. CA DATE 8-26-20.**