

Final Reclamation Inspection

August 10, 2020

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 335954

Inspection Document #: 697501865

Weld County, CO

NENW Section 18 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BRIDLE CREEK #2-18
Location ID: 335954



Photo 1. Photo taken from the location, facing East. Photo illustrates the one well that was drilled (123-14034) has been plugged. Based on field observations and records, this well was never drilled.