

# Interim Reclamation and Stormwater Inspection

August 10, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 455598

Inspection Document #: 697501867

Weld County, CO

NENE Section 18 T1N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Hingley /18H-A167  
Location ID: 455598



**Photo 1.** Photo taken from the northern location, facing Northwest. Photo illustrates a sediment trap stormwater BMP with a temporarily stabilized outlet. At the time of this inspection, BMPs appear to be in proper functioning condition. However, undesirable and noxious weed management is required. Refer to Photos 2-7 which also document weed management compliance issues.

Inspection Photos  
Location Name: Hingley /18H-A167  
Location ID: 455598



**Photo 2.** Photo taken from the northern location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: Hingley /18H-A167  
Location ID: 455598



**Photo 3.** Photo taken from the northeastern location, facing South. Photo illustrates a stabilized diversion ditch which is directed to a temporarily stabilized outlet.

Inspection Photos  
Location Name: Hingley /18H-A167  
Location ID: 455598



**Photo 4.** Photo taken from the northeastern location, facing West. Photo illustrates the Operator has repaired erosion along the northern fill slope.

Inspection Photos  
Location Name: Hingley /18H-A167  
Location ID: 455598



**Photo 5.** Photo taken from the northeastern location, facing South. Photo illustrates further weed management compliance issues.

Inspection Photos  
Location Name: Hingley /18H-A167  
Location ID: 455598



**Photo 6.** Photo taken from a portion of the northeastern fill slope. Photo illustrates the establishment of a List B Colorado noxious weed, Scotch thistle.

Inspection Photos  
Location Name: Hingley /18H-A167  
Location ID: 455598



**Photo 7.** Close up photo illustrates a List B Colorado noxious weed, Scotch thistle, flowering.

Inspection Photos  
Location Name: Hingley /18H-A167  
Location ID: 455598



**Photo 8.** Photo taken from the northeastern location, facing East. Photo illustrates further weed management compliance issues.