

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Pic 1 wellhead/pumpjack weeds throughout location.



Pic 2 weeds

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Pic 3 electric equipment / weeds



Pic 4 gas meter run

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Pic 5 weeds around separator




Pic 6 stained soil / mechanical issue



Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Pic 7 weeds in and around berm




Pic 8 weeds next to tanks.

Inspection Photos
Location Name: Guthrie 2
Location ID: 320188



Pic 9 weeds growing near tank



Pic 10 stained soil / mechanical issue.