

Inspection Photos
Location Name: Pergamos 3-11-7-60
Location ID: 429096



Photo 1 – Pumping Units



Photo 2 – Heater Treaters

Inspection Photos
Location Name: Pergamos 3-11-7-60
Location ID: 429096



Photo 3 – North Tanks – Content and Capacity have faded no longer visible.



Photo 4 – ECDs, Weeds

Inspection Photos
Location Name: Pergamos 3-11-7-60
Location ID: 429096



Photo 5 – Stained Soil at 4-3-7-60 Wellhead



Photo 6 – Stained Soil at Chemical Tank

Inspection Photos
Location Name: Pergamos 3-11-7-60
Location ID: 429096



Photo 7 – Stained Soil at Exhaust



Photo 8 – South Tanks – Content and Capacity have faded no longer visible.



Inspection Photos
Location Name: Pergamos 3-11-7-60
Location ID: 429096



Photo 9 – Weeds in Reclamation Area



Photo 10 – Weeds in Reclamation Area

Inspection Photos
Location Name: Pergamos 3-11-7-60
Location ID: 429096



Photo 11 – Weeds in Reclamation Area



Photo 12 – Weeds in Reclamation Area

Inspection Photos
Location Name: Pergamos 3-11-7-60
Location ID: 429096



Photo 13 – Weeds in Reclamation Area



Photo 14 – Weeds in Reclamation Area

Inspection Photos
Location Name: Pergamos 3-11-7-60
Location ID: 429096



Photo 15 – Weeds in Reclamation Area