

Inspection Photos

8/04/2020

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 1: Photo taken from the south end of the Location, facing southwest. Photo 1-4 provide an overview of the Location from southwest, west, north to northeast.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335117



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335117



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335117



Photo 5: Photo taken from the western interim areas of the Location, facing northwest. Interim reclamation appears to be progressing towards 1003 standards.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335117



Photo 6: North end of the Location, facing south. Photo provides an overview of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335117



Photo 7: North end of the Location, facing southwest. Photo provides an overview of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335117



Photo 8: Photo taken from the northeast end of the tank battery. Photo shows what appears to be a part of a monitoring well; Well in disrepair. It is unclear if monitoring wells are needed for the Location and require maintenance to ensure proper functioning condition, or proper abandonment.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335117



Photo 9: Continued from photo 8. Photo shows topsoil stockpile and drill cuttings. There does not appear to be BMPs in place to segregate cuttings from the topsoil.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335117



Photo 10: Photo taken from the northeast end of the tank battery. Photo shows second observed monitoring well. It is unclear if monitoring wells are needed for the Location and require maintenance to ensure proper functioning condition, or proper abandonment.