

Inspection Photos

8/10/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335667

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 1: Photo taken from the north end of the Location, facing north. Previous inspection required Operator to relocate excavated soils and to implement BMPs to mitigate transport/discharge of impacted materials pursuant to 1002.f rules. Photo shows soils have been relocated, however no BMPs have been implemented per 1002.f rules and corrective actions.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 2: Photo taken from the northwest end of the Location, facing west. See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 3: Photo taken from the northwest end of the Location, facing east. See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 4: Photo taken from the northern interim areas, facing south. See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 5: Photo taken from the northwest end of the Location, facing west. Photo shows Operator has implemented straw wattle BMPs; BMPs were observed to not have been installed in accordance with good engineering practices, and are not in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 6: Continued from photo 5. Photo shows BMPs have not been installed in accordance with good engineering practices, and are not in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 7: Continued from photo 5. Photo shows BMPs have not been installed in accordance with good engineering practices, and are not in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 8: Photo shows a cover has been placed over piping identified as “chemical lines”. Previous inspection required Operator to identify what the equipment is for and its current application for production activities on the Location. No resolution form has been submitted per the corrective action.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335667



Photo 9: Photo of riser on the west end of the Location. Previous inspection required Operator to identify what the equipment is for and its current application for production activities on the Location. No resolution form has been submitted per the corrective action.