

Inspection Photos

8/10/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 425805

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 1: Photo taken from the north end of the Location, facing south. Photo shows wells on Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 2: Photo shows riser remaining in the GPS position of the PA'd NPR H15 25C-10 596 well

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 3: Photo shows signage missing from several wells on Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 425805



Photo 4: Photo taken from the perimeter interim areas of the Location. Photo shows wattle BMPs have been maintained in proper functioning condition.