

Inspection Photos  
Location Name: Buchner 22H  
Location ID: 431634



Photo 1 – Location Sign at Entrance

Photo 2 – Pumping Unit

Inspection Photos  
Location Name: Buchner 22H  
Location ID: 431634



**Photo 3 – Tank Battery**

**Photo 4 – Flare and ECD, weeds**

**Inspection Photos**  
**Location Name: Buchner 22H**  
**Location ID: 431634**



**Photo 5 – Stained Soil at Pumping Unit**

**Photo 6 – Stained Soil at Exhaust, Weeds**

**Inspection Photos**  
**Location Name: Buchner 22H**  
**Location ID: 431634**



Colorado Oil and Gas Conservation Commission  
40.60387, -104.06668, 4873.0ft, 350°  
08/05/2020 12:28:01



Colorado Oil and Gas Conservation Commission  
40.60379, -104.06672, 4863.6ft, 3°  
08/05/2020 12:22:07

**Photo 7 – Stained Soil at Engine**

**Photo 8 – Stained Soil at Pumping Unit**

**Inspection Photos**  
**Location Name: Buchner 22H**  
**Location ID: 431634**



**Photo 9 – Weeds in Reclamation Area**

**Photo 10 – Weeds in Reclamation Area**

**Inspection Photos**  
**Location Name: Buchner 22H**  
**Location ID: 431634**



**Photo 11 – Weeds in Reclamation Area**



**Photo 12 – Weeds in Reclamation Area**

**Inspection Photos**  
**Location Name: Buchner 22H**  
**Location ID: 431634**



**Photo 13 – Weeds in Reclamation Area**

**Photo 14 – Weeds in Reclamation Area**

**Inspection Photos**  
**Location Name: Buchner 22H**  
**Location ID: 431634**



**Photo 15 – Unused Chemical Tank and Containment, Stand**