

Inspection Photos

Location Name: LAPP-66N64W /13SWSW

Location #: 309825



Photo #1

Lapp 13-33 (05-123-25429) Wellsite

Temporarily Abandoned | TA



Photo #2

Lapp 13-32, 13-24, 13-31, 13-33, 13-35 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Lapp 13-34, Lapp A 24-30D

Plugged & Abandoned | PA



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources