

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/11/2020

Submitted Date:

08/11/2020

Document Number:

699801591

FIELD INSPECTION FORM

Loc ID 451421	Inspector Name: De Paolo, Corey	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 28 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1401 SEVENTEENTH STREET #1401 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451416	WELL	PR	02/15/2018	OW	077-10445	Bruton 30-04E	PR
451417	WELL	PR	02/15/2018	GW	077-10446	Bruton 30-03W	PR
451418	WELL	PR	06/01/2018	GW	077-10447	Bruton 30-11W	PR
451419	WELL	PR	06/01/2018	GW	077-10448	Bruton 30-12E	PR
451420	WELL	PR	03/01/2018	GW	077-10449	Bruton 30-09E	PR
451423	WELL	PR	03/01/2018	GW	077-10450	Bruton 30-08W	PR
451424	WELL	PR	03/01/2018	GW	077-10451	Bruton 30-05E	PR
451425	WELL	PR	06/01/2018	GW	077-10452	Bruton 30-11E	PR
451426	WELL	PR	03/01/2018	OW	077-10453	Bruton 30-06W	PR
451427	WELL	PR	02/15/2018	GW	077-10454	Bruton 30-01W	PR
451428	WELL	PR	03/01/2018	GW	077-10455	Bruton 30-06E	PR
451429	WELL	PR	07/07/2018	GW	077-10456	Bruton 30-10E	PR
451430	WELL	PR	04/07/2018	OW	077-10457	Bruton 30-04W	PR
451432	WELL	PR	03/01/2018	GW	077-10458	Bruton 30-09W	PR
451433	WELL	PR	06/01/2018	GW	077-10459	Bruton 30-13E	PR
451434	WELL	PR	07/07/2018	OG	077-10460	Bruton 30-13W	PR
451435	WELL	PR	06/01/2018	GW	077-10461	Bruton 30-12W	PR
451436	WELL	PR	04/07/2018	OW	077-10462	Bruton 30-05W	PR
451437	WELL	PR	02/15/2018	GW	077-10463	Bruton 30-02W	PR
451440	WELL	PR	07/07/2018	GW	077-10464	Bruton 30-10W	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 8/11/20 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at LARAMIE ENERGY LLC Bruton /30-03 Pad, Location #451421 in Mesa County Colorado.

Refer to document #699801496 inspection conducted on 7/23/20. All previous corrective actions have been completed.

While there, I observed normal production operations.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 20		corrective date
Comment:			

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks by wellheads		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	500 gallon
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	451416	Type:	WELL	API Number:	077-10445	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451417	Type:	WELL	API Number:	077-10446	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451418	Type:	WELL	API Number:	077-10447	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451419	Type:	WELL	API Number:	077-10448	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451420	Type:	WELL	API Number:	077-10449	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451423	Type:	WELL	API Number:	077-10450	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451424	Type:	WELL	API Number:	077-10451	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451425	Type:	WELL	API Number:	077-10452	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	451426	Type:	WELL	API Number:	077-10453	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451427	Type:	WELL	API Number:	077-10454	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451428	Type:	WELL	API Number:	077-10455	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451429	Type:	WELL	API Number:	077-10456	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451430	Type:	WELL	API Number:	077-10457	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451432	Type:	WELL	API Number:	077-10458	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451433	Type:	WELL	API Number:	077-10459	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451434	Type:	WELL	API Number:	077-10460	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	451435	Type:	WELL	API Number:	077-10461	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451436	Type:	WELL	API Number:	077-10462	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451437	Type:	WELL	API Number:	077-10463	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	451440	Type:	WELL	API Number:	077-10464	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Waddles	Pass			
		Culverts	Pass			
		Sediment Traps	Pass			
		Ditches	Pass			
Berms	Pass					
Sediment Traps	Pass					
		Berms	Pass			
Check Dams	Pass					
		Gravel	Pass			
Gravel	Pass					
Waddles	Pass					
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801592	Photos for Insp. #699801591	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221795